

Sample Utility Co.

(555) 010-0142 · office@example.com

EQUIPMENT INSPECTION SHEET

Volvo EC145 Excavator — 10/05/2026

Equipment / vehicle	Volvo EC145 Excavator	Date	10/05/2026
Inspection by	Sample Inspector	Hours / mileage	4,182 hrs
Air temperature	Above 90° F	Oil filter #	VOE 11110683

Checklist

Walk Around

- Tracks/Wheels/Tires — OK
- Bucket — OK
- Cutting Edge/Teeth — NO: two teeth worn to the shank, need replacement
- Hydraulic Hoses — OK
- Fittings Greased — OK

Inside Cab

- Brakes — OK
- Backup Alarm/Horn — OK
- Seat Belt/Seat — OK
- Clean — OK

Engine/Fluids

- Oil Level — OK
- Coolant Level — OK
- Hydraulic Oil Level — OK
- Any Visible Leaks — OK

Semi/Trailer

- Hitch/Coupler — N/A
- Landing Gear — N/A
- Overall Trailer Condition — N/A

Notes

Example sheet rendered from sample data. A NO answer files an equipment issue with its note and photo; the real sheet prints every recorded answer and leaves out anything unanswered.

Generated 10/05/2026