

SANITARY SEWER I & I REPORT
10/05/2026 — Sample Project

Date of observation	10/05/2026	Project	Sample Project
Address / location	114 W Sycamore St	Report written by	Sample Utility Co.
Upstream MH	MH 101	Downstream MH	MH 102
Distance	40 ft from the upstream MH	Observation	Inflow

Observation

Inflow observed

- Gutters / Downspout
- No Cap on Cleanout
- Only occurs during rain
- Field verified or tested (do not test private property without permission)

Water entering the sanitary system that should be in the stormsewer

Notes

Example sheet rendered from sample data. A real sheet prints exactly what the filing recorded and leaves out anything it did not.