

IMPROPER UTILITY & ILLEGAL DUMPING REPORT
10/05/2026 — Sample Project

Date of observation	10/05/2026	Project	Sample Project
Address / location	Alley behind 300 block, E Linden St	Report written by	Sample Utility Co.
Upstream MH	MH 214	Downstream MH	MH 215
Distance from US MH	120 ft		

Observation

Improper utility installation

- Utility type: Water
- Watermain closer than 2 feet
- Touching Mainline

Illegal dumping

- Large Amounts of Grease
- Concrete Slurry

Who was informed

- City officials informed
- Date informed: 10/05/2026

Notes

Example sheet rendered from sample data. A real sheet prints exactly what the filing recorded and leaves out anything it did not.

Generated 10/05/2026