

JOB SAFETY ANALYSIS
10/05/2026 — Sample Project

Date of observation	10/05/2026	Project	Sample Project
Report written by	Sample Utility Co.	Location	MH 101 to MH 102
Work covered	Open-cut repair of the line segment	Signed	10/05/2026

Job Safety Analysis

The job, step by step

- Step 1: Set traffic control — Hazard: passing traffic — Control: cones, signage, and a spotter
- Step 2: Excavate to the pipe — Hazard: cave-in — Control: trench box in place before entry
- Step 3: Replace the section — Hazard: pinch points — Control: gloves, and hands clear of joints

Signatures

- Sample Crew Lead
- Sample Worker One
- Sample Worker Two

Signed 10/05/2026 — drawn signatures appear at the end of this sheet.

Notes

Example sheet rendered from sample data. A real sheet prints exactly what the filing recorded and leaves out anything it did not.